

**From:** [Miller, Garyg](#)  
**To:** [Satya Dwivedula](#); [Bob Allen](#); [Linda Henry](#); [Garry McMahan](#); [Leah Oberlin \(loberlin@poha.com\)](#); [angela.sunley@glo.texas.gov](#); [Walker, Tina \(DSHS\)](#)  
**Cc:** [Walters, Donn](#)  
**Subject:** FW: San Jacinto River Waste Pits Superfund Site - Potential Cap Deficiencies  
**Date:** Tuesday, May 24, 2016 3:39:00 PM  
**Attachments:** [SJWP dive Summary report Apr 2016.pdf](#)

---

FYI.

---

**From:** Miller, Garyg  
**Sent:** Tuesday, May 24, 2016 3:32 PM  
**To:** David Keith <dkeith@anchorqea.com>  
**Cc:** Sanchez, Carlos <sanchez.carlos@epa.gov>; Meyer, John <Meyer.John@epa.gov>; Foster, Anne <foster.anne@epa.gov>; Walters, Donn <walters.donn@epa.gov>; Todd, Brandi <Todd.Brandi@epa.gov>; Leos, Valmichael <Leos.Valmichael@epa.gov>  
**Subject:** San Jacinto River Waste Pits Superfund Site - Potential Cap Deficiencies

David,

Please see the attached dive team summary report. During their inspection of the cap at the San Jacinto River Waste Pit Superfund Site in April 2016, the EPA Dive Team found areas located in the west part of the cap where the armor rock was missing. The sizes of these areas varied between approximately 9 square feet and 100 square feet.

In accordance with the Operations, Monitoring, and Maintenance Plan, please prepare a repair plan, including delineation of the extent of the armor deficient areas for the above referenced areas, and including quality assurance and quality control procedures. The repair plan should also include an expedited schedule and a description of the initial construction and inspection activities and results for this area.

Please let me know if you have any questions on this.

Regards,

Gary Miller  
Remedial Project Manager  
EPA Region 6 Superfund Division, TX/Ark Section  
214-665-8318  
[miller.garyg@epa.gov](mailto:miller.garyg@epa.gov)



9807401